## Chain Tension Assembly - 800cc, UTV, Hisun - 70A9527 - PBC1182F1







Rating: Not Rated Yet **Price** 

\$32.26

Ask a question about this product

Description

Chain tensioner assembly applies to (and is not limited to) 800cc engines. Commonly used for (but not limited to) 800cc engines, such as the Hisun 800cc UTVs, as well as many other clones, rebrands and similar displacement machines.

These machines are commonly manufactured by Chongqing Huansong Industries (Group) Co., Ltd. and distributed by a range of exporters, importers and distributors under such brands as: Hisun, Bennche, Coleman, Massimo, Qlink, Menards Yardsport, Big Muddy, Powermax, Nordik, TSC, Rural King, Cub Cadet, Excalibur, US Titan / Supermach, Precision, JMC and many others.

Common Hisun model names are primarily listed as variations of "Hisun 800cc UTV", "Hisun HS800UTV" and "HS800UTV EPA". Common listed Hisun tensioner assembly part number is 14500-004-0000 and formal description is "TENSIONER ASSY". Also applies to some other variations of Hisun models.

Common Nordik model names are primarily listed "Nordik NK 800 U (NK800U)". Common listed Nordik chain tension assembly part number is 14500-004-0000 and ERP part number is 14500-004-0000. Also applies to some other variations of Nordik models.

Common Powermax model names are primarily listed as "Powermax Roughrider 800 UTV". Common listed Powermax chain tension assembly part number is 14500-004-0000 and ERP part number is 14500-004-0000. Also applies to some other variations of Powermax models.

Manufacturer PN: 14500-004-0000
Manufacturer PN: 14500-F39-0000
Manufacturer PN: P007000145300000